


Case Study



Tree Preservation Order

A site affected by a tree preservation order. An existing dwelling was to be replaced with a larger one. The council had raised concerns and were resistant to the proposal.

Tree Survey

A BS5837 compliant site survey was undertaken paying particular attention to the trees the subject of the TPO.

Expert Advice

We were able to 'make the case' for the development based on our expert knowledge of how trees interact with soils. We undertook airspade investigations to 'prove' that significant tree roots were not present and allow the development to proceed.

“It's simple, without the advice of Tamla Trees we would not have got our planning permission, many thanks.”

Client Testimonial